


2017 Fire Inspection – Residential Housing & SURC

- 24 Residential Housing Buildings -



Miscellaneous Findings (48%)

- Fire door wedged open (2 reported)
- Extension cord used as permanent wiring (2 reported)
- Fire door de-laminating (1 reported)
- Egress pathway obstructed (1 reported)
- Multiplug adapter in use (1 reported)
- Electrical panel obstructed (2 reported)
- Fire door disabled - closing mechanism (1 reported)
- Exit pathways obstructed (1 reported)
- Maintain vertical clearance below fire sprinklers (1 reported)