



Division 140000

Conveying System

DESIGN GUIDE

Contents – Division 070000:
140000 Elevators (Hydraulic)

140000 Elevators (Hydraulic)

1 General

1.1 General

- A. Any elevator manufacture must have a local rep for emergency service response within 60 minutes during the first year warranty period.
- B. New buildings should be designed for two elevators servicing each floor for redundancy, should one elevator go down, there would be one available for use by the handicapped.
- C. Although not required by code, consideration should be given to sizing one elevator in each building large enough to accommodate an emergency services gurney.
- D. CWU must OWN all products, including software, to reprogram the microprocessor should these programs be lost or need changing after the first year warranty period.
- E. Door keys will be provided for each elevator and located in the elevator equipment room.
- F. Additional as-built drawings of each elevator are to be provided in each elevator equipment room.